



## ALL APPROVED PERSONS ALL APPROVED CRANE CONTRACTORS

## LIMIT ON THE SERVICE LIFE OF PILING MACHINES

This circular is to follow up on the enquiries on the circular LE 9/99 dated 23 Dec 1999 on the "limit on the years of service of mobile cranes".

2. As stated in the circular, cranes that are of a similar construction to that shown in the Appendix of the SS CP 37 are affected by the policy to limit the years of service of mobile crane. In this regard, piling rigs that are **attached to a crawler crane** (refer to the sketches 1, 4, 5 and 6) will be included in this category.

3. Hydraulic boring machines, hammer/ percussion piling machines or machines that are of a similar construction (as shown in the sketches 2 & 3) that are mounted directly onto the chassis without the lattice boom are not affected by this policy.

**SNG WEE KIAT, SILAS** for CHIEF INSPECTOR OF FACTORIES

Date of Issue	Classification:	Circular No:	CIF A32.4.1
31 Jan 2001	Mobile Cranes	OSD/ ENG CIR / LE 1/01	Page 1 of 2



Date of Issue	Classification:	Circular No:	CIF A32.4.1
31 Jan 2001	Mobile Cranes	OSD/ ENG CIR / LE 1/01	Page 2 of 2